

=== Line Inspection Report ===

19SEP14 11:50AM

City of Hollister

--- LOCATION HEADER ---
INSP DATE :9/19/14
LOCATION :Mapleton
LOCATION :Fremont Aly
UPS MANHOLE:
DNS MANHOLE:Sewer line
CREW WORK :JM/BC

----- LINE DATA -----
VEWER TYPE :
SURFACE :
INSP LENGTH:
PIPE TYPE :Sewer Line
PIPE SIZE :6in
PIPE LENGTH:
OPERATOR :JM
INSPECTOR :
DIRECTION :W/B

Record 001: 0000.0F
START INSPECT
Record 002: 0027.5F
ROOTS PRESENT
Record 003: 0027.5F
OFFSET JOINT
Record 004: 0061.4F
ROOTS PRESENT
Record 005: 0078.8F
LATERAL SERVICE
Record 006: 0080.7F
LATERAL SERVICE
Record 007: 0092.8F
LATERAL SERVICE
Record 008: 0131.7F
ERODED PIPE
Record 009: 0144.6F
BROKEN PIPE
Record 010: 0162.9F
LATERAL SERVICE
Record 011: 0168.5F
LATERAL SERVICE
Record 012: 0196.5F
BROKEN PIPE
Record 013: 0213.0F
LATERAL SERVICE
Record 014: 0261.7F
LATERAL SERVICE
Record 015: 0272.7F
LATERAL SERVICE
Record 016: 0303.7F
LATERAL SERVICE
Record 017: 0313.3F
~~LATERAL SERVICE~~
Record 018: ~~0412.3F~~
MANHOLE
Record 019: 0412.3F
END INSPECT

299.6
~~309.6~~ LATERAL SERVICE N/S

=== Line Inspection Report ===

31JUL12 01:52PM

City of Hollister

--- LOCATION HEADER ---
INSP DATE :7/31/12
LOCATION :Mapleton st
LOCATION :Fremont al
UPS MANHOLE: 6inch
DNS MANHOLE: 6inch
CREW WORK :M.E ,pepe

----- LINE DATA -----
VEWER TYPE :
SURFACE :
INSP LENGTH:
PIPE TYPE :SEWER Line
PIPE SIZE : 6in
PIPE LENGTH:
OPERATOR :Mario E
INSPECTOR :
DIRECTION : W/B

- Record 001: 0000.0F
START INSPECT
- Record 002: 0029.4F
OFFSET JOINT
- Record 003: 0032.7F
SAG IN PIPE
- Record 004: 0061.7F
LATERAL SERVICE
- Record 005: 0078.8F
LATERAL SERVICE
- Record 006: 0078.8F
ROOTS PRESENT
- Record 007: 0080.6F
LATERAL SERVICE
- Record 008: 0080.6F
GREASE PRESENT
- Record 009: 0092.8F
SAG IN PIPE
- Record 010: 0092.8F
LATERAL SERVICE
- Record 011: 0132.8F
SAG IN PIPE
- Record 012: 0144.2F
BROKEN PIPE
- Record 013: 0162.2F
LATERAL SERVICE
- Record 014: 0163.9F
LATERAL SERVICE
- Record 015: 0167.8F
LATERAL SERVICE
- Record 016: 0212.0F
LATERAL SERVICE
- Record 017: 0260.7F
LATERAL SERVICE
- Record 018: 0271.5F
LATERAL SERVICE
- Record 019: 0271.5F
GREASE PRESENT
- Record 020: 0302.9F
LATERAL SERVICE
- Record 021: 0302.9F
DROP SERVICE
- Record 022: 0317.0F

=== Line Inspection Report ===

03OCT13 03:46PM

City of Hollister

----- LINE DATA -----

--- LOCATION HEADER ---
INSP DATE :10/3/13
LOCATION :360 Mapleton
LOCATION :
UPS MANHOLE:W/B
DNS MANHOLE:
CREW WORK :JM/AF

VEWER TYPE :
SURFACE :
INSP LENGTH:
PIPE TYPE :Sewer Line
PIPE SIZE :6in
PIPE LENGTH:
OPERATOR :JM/AF
INSPECTOR :
DIRECTION :W/B

Record 001: 0001.2F
START INSPECT
Record 002: 0027.3F
OFFSET JOINT
Record 003: 0059.7F
ROOTS PRESENT
Record 004: 0061.1F
LATERAL SERVICE
Record 005: 0077.8F
LATERAL SERVICE
Record 006: 0079.9F
LATERAL SERVICE
Record 007: 0161.7F
LATERAL SERVICE
Record 008: 0167.2F
LATERAL SERVICE
Record 009: 0211.6F
LATERAL SERVICE
Record 010: 0260.1F
LATERAL SERVICE
Record 011: 0270.7F
LATERAL SERVICE
Record 012: 0301.9F
LATERAL SERVICE
Record 013: 0307.3F
GREASE PRESENT
Record 014: 0311.5F
LATERAL SERVICE
Record 015: 0369.4F
GREASE PRESENT
Record 016: 0383.0F
GREASE PRESENT
Record 017: 0397.5F
LATERAL SERVICE
Record 018: 0408.2F
GREASE PRESENT
Record 019: 0410.8F
MANHOLE
Record 020: 0372.5F
END INSPECT

=== Line Inspection Report ===

02AUG12 09:12AM

City of Hollister

----- LINE DATA -----

--- LOCATION HEADER ---

INSP DATE :8/01/12
LOCATION :Community
LOCATION :Center
UPS MANHOLE: 6inch
DNS MANHOLE: 6inch
CREW WORK :M.S,A.R

VEWER TYPE :
SURFACE :
INSP LENGTH:
PIPE TYPE :SEWER Line
PIPE SIZE : 6in
PIPE LENGTH:
OPERATOR :Albert
INSPECTOR :
DIRECTION : W/B

Record 001: 0000.0F

START INSPECT

Record 002: 0002.3F

LATERAL SERVICE

Record 003: 0015.8F

SAG IN PIPE

Record 004: 0038.3F

LATERAL SERVICE

Record 005: 0056.9F

LATERAL SERVICE

Record 006: 0076.9F

OFFSET JOINT

Record 007: 0088.6F

LATERAL SERVICE

Record 008: 0110.9F

SAG IN PIPE

Record 009: 0146.4F

SAG IN PIPE

Record 010: 0154.3F

OFFSET JOINT

Record 011: 0160.8F

SAG IN PIPE

Record 012: 0172.7F

OFFSET JOINT

Record 013: 0176.5F

OFFSET JOINT

Record 014: 0200.7F

LATERAL SERVICE

Record 015: 0214.0F

LATERAL SERVICE

Record 016: 0223.1F

GREASE PRESENT

Record 017: 0261.0F

SAG IN PIPE

Record 018: 0276.9F

SAG IN PIPE

Record 019: 0297.0F

LATERAL SERVICE

Record 020: 0317.0F

GRAVEL PRESENT